

A B S T R A C T

MARKING OF PIPE JOINTS

An improved method of permanently marking the location of a tubular joint, the method including creating a cavity into the end surface of one of the tubular ends that are to be joined by a forge weld or screw thread connection, inserting a marker into said cavity and subsequently joining the tubular ends.